Structure	Canal Merrimack River HAER/CEHR
. Moor's Falls (3 locks)	Navigation Condition Poor
State/Province N. H. Count HILLSboro	Designer(s) Union Locks & Canal Co.
M&y/Town Litchfield (See below)	Contractor/Builder Union Locks & Canal Co.
streeAccessible only by water today.	Source of Material Local
Associated Waterway Merrimack River	Before tes of construction
TOPOGRAPHIC MAP Manchester South Quad 72	Start 1814 Rebuilding ??/
UTM Coordinates 298.9/4751.4	Completion by 1814 Abandon Bresume 1850's

This set of three locks on the Merrimack River were constructed in much the same manner as other river locks, in that they are built within the river banks. This set of rapids is the longest of all on the system (as such). Built under difficult conditions even in those early years, leaving you with thoughts as to how it was ever done. The slabs of heavy granite and how they mannexxxix maneuvered them to these sites is remarkable. This type of work could only be done during a period of low water, no question about that. These 3 locks provided a by-pass of long rapids. Located on the Litchfield or(east side) of the river. All boats had to use these locks going north or south. These were all single locks.

Description (Visibile Remains at the site):

Access to these 3 locks by land is difficult and not recommended. The best and easiest route is by cance in late fall when the river water is low and the foliage is gone. Launch cance at about Reeds Ferry and paddle northeast to the Litchfield shore. Locks will be on your right. Lock walls are very descernable, the straight lines of chambers can be observed, but generally filled with rubble stone and sand, plus slab granite tossed around by spring ice floes. These locks are spaced about as follows— from 1st lock to 2nd lock the canal was about 2500 ft.More or less. 2nd lock to 3rd lock was a small basin. Third lock to river. DO NOT ATTEMPT TO DO THIS ALONE!!!!

Other works or events associated with site:

No other works associated with with this site, or events that I know of. These locks(so called) I believe, have no sign of ever using balance beams but should be considered as sluice gates, using only the lower end of each lock with a drop gate, then water pressure from its canal forces boat out.

Present Property Owners: Location of Deed Description: Unknown Unknown Bibliography (Published, unpublished mss, maps, photographs): Very little <u>detail</u> is found regarding any locks on this system. Other than mentioning the artifact. Concord Historical Society has 3 books. "The Merrimack"by Rhinehart; "River of Broken Waters" by J.W.Browne(1918); "The Merrimack River" by Meader (1869); The American Canal Society will have phptos taken in 1974-75; ???? Agencies, Individuals Interested in Preservation/Restoration: National Register/CEHR, Other Recognition: Due to condition of locks at this site I would doubt if anyone is much interested other than ACS. Very doubtful Investigation made by: Alden W. Gould (ACS) Date: July 974-75 Address: 12 Shady Crest Drive, Nashua, N.H. 03060 RETURN TO: Pater Statt