American Canal Society Canal Index

CANAL	STATUS					ACS
						HAER
STATE/PROVINCE				LENGTH		LIFT LOCKS
		DATES IN USE	CANAL	SLACKWATER	TOTAL	No./SIZE
COUNTIES:						
LOCATION (Endpoints of Canal):	١	1				
	ENLARGEMENTS	-				
	E	2				
TOPOGRAPHIC MAPS:	RG	3				
	ΙŽ	4				
HISTORICAL SIGNIFICANCE:	ш		1			
PHYSICAL DESCRIPTION:						
NAMES & ADDRESSES OF GROUPS CONCERNED WITH CAN	IAL'S	PRESERVATION/RESTOR	ATION:			
BIBLIOGRAPHICAL SUMMARY:						
INDUDUCUED DECORDS BUSTOS ES AUTOS (OFFICE CO.	D	ADC Land D1 11"		Libraria (-)		
UNPUBLISHED RECORDS, PHOTOS, DRAWINGS (CEHR, HAE	к, н	ADO. LOCAI OF REGIONAL Hist	orical Societies,	Libraries, etc.):		
EXISTING OR RECOMMENDED LANDMARK STATUS (CEHR,	Natio	onal Register, ETC.):				
]		÷ , · ,				
Investigation made by:						Date:
Address:						

Black River Canal Structures

			1.10		Revised 11/9/08
Lock	Mileage	Group Location	Lift	Condition	Notes
	0.00	Junction with Erie		D	
1	0.08	Rome	10' north	Buried	
2	0.29	Rome	10' north	Buried	
3	0.44	Rome	10' north	Buried	
4	0.86	Rome	10' north	Buried	
5	1.52	Rome	10' north	Buried	
6		Rome	10' north	Buried	
new 7		Below Delta Da		Intact	
	South junc	tion between new bypass a	_		
		New Mohawk Aqueduct - c	oncrete 4 span	Intact	
new 8		3 Beside Delta Da		Intact	
new 9		Concrete Beside Delta Da	am	Intact	
new 10		Combines Beside Delta Da	am	Buried	
	original rout	e -			
7	5.05	Below Delta Da	m 10' north	Removed	
8	5.55	Delta Lake	11' north	Submerged	In Delta Lake
		Mohawk Aqueduct - stone	piers & abutments,	wood trunks, four 40)' spans.
9	5.68	Delta Lake	12' north	Submerged	In Delta Lake
10	5.82	Delta Lake	11' north	Submerged	In Delta Lake
11	5.98	Delta Lake	11' north	Submerged	In Delta Lake
12	6.08	Delta Lake	11' north	Submerged	In Delta Lake
13	6.54		8' north	Buried by Rte. 46	
	North junct	ion between new bypass ar	nd original canal	·	
14	8.64		8' north		
15	8.78		8' north		some stonework remains
16	8.94		10' north	Intact	next to Rte 46 in Westernville
17	10.43	just south of cre	ek 8' north	partly fallen in	near Rte. 46
		k Aqueduct - stone piers &			
18	11.04	•	10' north	,	at edge of woods
19	11.28		8' north	intact	behind barn
20	11.44		10' north	Intact	nr Rte. 46 south of N. Western
21	11.59		10' north	Intact	nr Rte. 46 south of N. Western

Lock	Mileage	Group	Location	Lift	Condition	Notes	
22	12.15			10' north	Intact	E. Rt. 46, south of Stringer Crk	
Stringer Creek Aqueduct - stone piers & abutments, wood trunks, four 18' spans gone							
	Side Hill Ro	oad Bridge					
23	13.02			10' north	no noticable remain	ns	
24	13.38			10' north	no noticable remain	ns	
	North end	of Hillside Roa	ıd - road bridge wa	is also a chan	ige bridge		
25	13.87			10' north	Some remains		
		of Hillside Roa	ad, canal crossed L	•	a six span aqueduct		
26	14.26			10' north		At least two of these locks are	
27	14.63			10' north		visible on aerial photos, but	
28	14.92			10' north		they are on the opposite side of	
29	15.07			10' north		Lansingkill from Rte. 46	
	Arch Culve						
	Road Bridg	je					
30	15.51			10' north	Intact	next to Rte. 46	
31	15.71			10' north		no remains	
32	16.13			10' north	Intact	Behind house along Rte. 46	
33	16.52			10' north			
34	16.74			10' north	Intact	near Rte. 46	
35	16.90			10' north	Intact	near Rte. 46	
36	17.40			10' north	partly intact	next to Rte. 46 - start of trail	
37	17.18			10' north	Intact	next to Rte. 46	
38	17.34			10' north	Intact	next to Rte. 46	
39	17.53			10' north	Intact		
40		5		10' north	Intact		
41		combines		10' north	Intact		
42		00111011100		10' north	Intact		
43				10' north	Intact		
44	17.83	3		10' north	filled with earth		
45		combines		10' north	visible		
46		00111011100		10' north	visible		
47	18.28			10' north			
48	18.63			10' north			
49	18.73			10' north			
50	18.84			10' north			
51	19.07			10' north			

Lock	Mileage	Group	Location	Lift	Condition	Notes
52	19.23			10' north		_
53	19.37			10' north		
54	19.54			10' north		
55	19.74			10' north		
56	19.86			10' north		
57	20.07			10' north		
58	20.26	3		10' north		
59		combines		10' north		
60		COMBINES		10' north		
61	20.56			10' north		
62	20.82			10' north		
	Bulkhead 8	& Waste Weir	into Lansingkill Fe	eder - in use t	oday	
63	21.11			10' north	Intact	Water flows over floor
64	21.24			10' north	Intact	Water flows over floor
65	21.78			10' north	Intact	Water flows over floor
66	22.10			10' north	Intact	Water flows over floor
67	22.42			10' north	Intact	Water flows over floor
68	22.53			9' north	Intact	Water flows over floor
69	22.64			9' north	Intact	Water flows over floor
70	22.82			9' north	Intact	South end, Boonville summit
Forestpor	t Feeder Jun	nction			North end of water	ered main canal
71	25.13			10' south	Buried	North end, Boonville summit
72	25.63			10' south		
73	26.33			10' south		
74	26.47			10' south		
75	27.16			10' south		
76	27.32]		10' south		
77		4		10' south		
78		Combines		10' south		
79				10' south		
80	27.89			9' south		
81	28.03			9' south		
82		4		9' south		
83		Combines		9' south		
84				9' south		

Lock	Mileage	Group	Location	Lift	Condition	Notes
Sugar Rive	r Aqueduct					
85	28.66		Center of Route 12	10' south	Intact	
86	28.91		Center of Route 12	11-1/2' south	Intact	
87	29.10		Center of Route 12	10' south	Intact	
88		4	Center of Route 12	10' south	Intact	
89		Combines	Center of Route 12	10' south	Intact	
90			Center of Route 12	10' south	Intact	
91	29.32		Center of Route 12	10' south	Intact	
92	30.63			10' south	Under Route 12?	
93	31.08			10' south	Under Route 12?	
94	31.43			10' south	Under Route 12?	
95	32.64			10' south	Under Route 12?	
96	32.09		Port Leyden	10' south	Intact next to Route	12
97	33.16		Near Port Leyden	10' south	Under Route 12	
98	33.41		Near Port Leyden	10' south	Intact next to Route	12
99	33.86	1 3 1	Near Port Leyden	10' south	Top stones fallen	Rough, overgrown
100		Combines	Near Port Leyden	10' south		surroundings, next to road
101		Combines	Near Port Leyden	11' south		
102	34.04		Near Port Leyden	10-1/4' south		Outlet to Black River
103	35.13	3	Lyons Falls	4' south	Buried	
104		Combines	Lyons Falls	10' south	Buried	
105			Lyons Falls	10' south	Buried	
106	35.38	2	Lyons Falls	11' south	Intact	Private Property
107			Lyons Falls	11' south	Intact	Private Property
108	35.49	2	Lyons Falls	12' south	Intact	Private Property
109	35.52	Combines	Lyons Falls	12' south	Intact	Private Property
		Lock & Dar	m at Otter Creek		Dam gone, but lock	may have remains
		Lock & Dar	n at Bushes Landing		Dam gone, but lock	may have remains
		Dam at Ca	rthage			In use